I^st & final bill

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

63160

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency..... Sri. Girish. S .....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Name of work :- Maintainance of Foot path & construction of SSM wall and kerb in ward no. 18. in Shettyhalli Sub-division.						
	Job code :- 013-18-000039						
	A.A :- EE/DD/AS/230/17-18, Dt :- 07.11.2017.						
	T.S :- EE/DD/TS/86/17-18, Dt :- 07.11.2017.						
	Work order :- EE/DD/WO/242/17-18, Dt :- 27.02.2018.						
	Est cost :- Rs. 10.00 Lakhs.						

Scanned by CamScanner

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

63163

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Number	Dimensions Length	Breadth	Depth	Contents	Reference to last Measurement
1	2	3	4		5	6	7	8
	graded granite metal coarse aggregates @ 0.64 cum & fine aggregates @ 0.43 cum machine mixed with super plasticizer @ 8 kg/m³. It is completed as per specification.						
	For pillars	42	× 0.45	× 0.60	× 0.46	4.54	
	For coping	1	× 15.00	× 0.60	× 0.10	0.90	
		1	× 17.46	× 0.60	× 0.10	1.04	
		1	× 12.60	× 0.60	× 0.10	0.76	
		1	× 15.00	× 0.60	× 0.10	0.90	

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರವರು
ಶಿವಾಜಿನಗರ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

Scanned by CamScanner

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

63165

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc. of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	cost of all materials, labours. It is completed as per specification						
		1	× 15.00	× —	× 1.80	27.00	
		1	× 17.40	× —	× 1.80	31.32	
		1	× 12.60	× —	× 1.80	22.68	
		1	× 15.00	× —	× 1.80	27.00	
		1	× 15.00	× —	× 1.80	27.00	
		1	× 13.00	× —	× 1.80	23.40	
						158.40	

Clid + Re

14/8/18

EXECUTIVE ENGINEE
Brihat Bangalore Mahanagara Palik
Dasarahalli Division, Bangalore

Scanned by CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	brushing to give an even shade after cleaning oil, grease dirt & other foreign matter. It is completed as per specification.						
		1×	15.00	–	1.80	27.00	
		1×	17.40	–	1.80	31.32	
		1×	12.60	–	1.80	22.68	
		1×	15.00	–	1.80	27.00	
		1×	15.00	–	1.80	27.00	
		1×	13.00	–	1.80	23.40	
						158.40	Sqm

Clerk

24/8/18

ಸರಾಯಿಪಾಳ್ಯ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಪೆಟ್ಟಿಕಳ್ಳ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಮಿಸ್ಸಾ.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

Audited and admitted for Rs. 948549-00

Passed by Cheque for Rs. 923411-20

Serial No. 25138-00

Name of work

Name of Contractor of nature of Agency

Date of commencement of work

Exa. Engineer

M. A. R. 57 (Rule 116) No. D

Measurement Book

63167

From To

B.B.M.P. Basarahalli Division

Date	Full description, etc, of work	Number	Dimensions: Length	Dimensions: Breadth	Dimensions: Depth	Contents	Reference to last Measurement
1	2	3	4	5	6	7	8
	@ ₹. 88.56/sqm					—	₹. 14028=00
							948549=00
					Total	—	₹. 948525=00

Certificate

Certified that the work is done Saticifactorily.

24/VIII/16

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೆಸ್ಕಾಂ ಉಪವಿಭಾಗ, ಬಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8



Index

- Boundary wall with chain link fencing

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner